



Industry: Agriculture

- A milling company experienced Sprocket failure.
- *Martin* delivered a replacement Sprocket within hours of the original call.

Documented Cost Savings - \$96,000



Product

Martin sets the standard when it comes to Sprockets. *Martin* stocks more Sprockets in more sizes than any other manufacturer. In addition, Martin offers same-day re-bores, alterations and made-to-order Sprockets in days, not weeks.

The *Martin* brand is synonymous for reliable Roller Chain Sprockets made from quality North American steel.

Common Applications

Agriculture, Aggregate and Cement, HVAC, Oil & Gas, Food & Beverage, Mining, Pulp and Paper, Lumber and Forestry, Wastewater.

Challenge

- Production at a corn processing plant halted when a Roller Chain Sprocket for a germ dryer failed.
- Germ is a section of the corn that is removed to be dried before the corn oil is extracted.

Solution

- Acting quickly to help the client minimize downtime and lost productivity, *Martin* pulled a 306lb Sprocket from inventory and met a courier within two hours of the original phone call.
- The courier delivered the Sprocket right away, ensuring the customer could resume operations.

Impact

- Because of *Martin's* known reliability for any after hours emergencies, *Martin* was able to provide the corn processing plant a total documented cost savings of \$96,000.



Bottom-Line Results

Downtime Avoidance

(\$4,000.00 Downtime Cost per Hour X 24.00 Potential Downtime Hours X 1 Machine)

Total Documented

Cost Savings - \$96,000.00

Learn more about *Martin* and Roller Chain Sprockets at:
www.martinsprocket.com - 817.258.3000